DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-017172 Address: 333 Burma Road **Date Inspected:** 22-Sep-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Peng Wen Jian No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector Larry Viars was present during the times noted above for observations relative to the work being performed.

Bay 16-

This QA Inspector observed the following work in progress: Flux Cored Arc Welding (FCAW) of OBG Steel Barrier weld, W5-SB1-001-012. ZPMC welder was identified as 037944. ZPMC QC was identified as Guo Pan. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2132.

Flux Cored Arc Welding (FCAW) of OBG Steel Barrier weld, W5-SB1-013-015. ZPMC welder was identified as 037944. ZPMC QC was identified as Guo Pan. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2132.

Bay 19-

Flux Cored Arc Welding (FCAW) of OBG Suspender Bracket SB90E weld, SB020-090-001. ZPMC welder was identified as 062749. ABF CWI was identified as Peng Wen Jian. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2232-TC-U4b-F.

Flux Cored Arc Welding (FCAW) of OBG Suspender Bracket SB88E weld, SB020-088-005. ZPMC welder was identified as 062783. ABF CWI was identified as Peng Wen Jian. The welding appeared to be in conformance

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

with welding procedure specification, WPS-B-T-2232-TC-U4b-F.

Flux Cored Arc Welding (FCAW) of OBG Suspender Bracket SB86E weld, SB020-086-008. ZPMC welder was identified as 062762. ABF CWI was identified as Peng Wen Jian. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2232-TC-U4b-F.

Bay 14-

This QA Inspector observed the following work in progress: Flux Cored Arc Welding (FCAW) of OBG Segment 13AE Vortex Plate weld, VP3007-001-011. ZPMC welder was identified as 067876. ZPMC CWI was identified as Zhong Guo Hui. ZPMC CWI was identified as Geng Wei. The welding appeared to be in conformance with welding procedure specification, WPS-B-T-2232-TC-U4b-F.

Blast Bay 1-

Caltrans Quality Assurance (QA) Inspectors performed random visual inspection of OBG segment 11CW lower section base metal and weld surfaces. Areas requiring light grinding were marked for ZPMC personnel. Items which require repair were recorded for future repair.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation between QA and QC occurred this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150 0042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer